



Words of wisdom

"I fired my new FMK yesterday at an indoor range here in Springdale. Really performed way beyond my expectations. Did much better with it than with any of my other 9mm."

– Geary D.

Receive latest product updates and special offers from FMK.

Enter your email below

you@example.com

Sign up!

Product Safety and Recall Notice

FMK Firearms 9C1 with Fast Action Trigger & 9C1 Fast Action Trigger Kit

In 2013 we determined that, under certain circumstances, the 9C1 Pistols fitted with Fast Action Triggers could discharge when dropped.

Consumer safety is our first priority. We will retrofit all affected 9C1 Pistols with Fast Action Triggers and all Fast Action Trigger kits at our factory at no charge to our customers. The retrofit will include removal of the affected Fast Action Trigger and installation of the new Elite Trigger 804. Old parts will not be returned.

Do not load or fire your 9C1 pistol with the Fast Action Trigger until it has been factory retrofitted with these new parts, the pistol could DISCHARGE if dropped with a round in the chamber.

HOW TO DETERMINE IF YOUR TRIGGER NEEDS THE RETROFIT:

AFFECTED FAST ACTION TRIGGER



Original Fast Action Trigger – Safety protrudes slightly. Needs Retrofit!

NEW FAST ACTION TRIGGER 316



New Fast Action Trigger 316 – Safety protrudes significantly. Pistol Does Not Need Retrofit (Identified by '316' Markings)

ELITE TRIGGER 804



ELITE Trigger 804 – Safety protrudes significantly. Pistol Does Not Need Retrofit (Identified by '804' Markings)

DAO TRIGGER DOES NOT NEED RETROFIT



DAO Trigger can be identified by shorter trigger safety which does not break through the bottom of the trigger. DAO trigger rotates further forward. This Pistol does not need retrofit.

If you own a Fast Action Trigger kit or 9C1 pistol with a Fast Action Trigger which does not bear the engraving "316" please contact us immediately to arrange for replacement of your Fast Action Trigger Assembly.

If your 9C1 pistol has a Fast Action Trigger and it is engraved with "316" or you have a Double Action Trigger or Elite Trigger 804 it does not need to be retrofitted.

We will ask for your Name, Address, Telephone Number, 9C1 Serial #, and provide to you an RMA # for tracking purposes.

Email: FATrecall@fmkfirearms.com
FAX: 281-548-3535
Phone: 800-420-7511
(Available Monday – Friday, 9:00 AM to 5:00 PM PST)

Thank you,
FMK Firearms, Inc.

Share this:



Receive latest product updates and special offers from FMK.

Enter your email below you@example.com

Sign up!