

**ATTENTION**  
**IMPORTANT SUB-2000 SAFETY RECALL NOTICE**

We have recently identified an issue with the heat treatment of certain steel tubes received from a third-party supplier from which the barrels for a limited number of Kel-Tec SUB-2000 rifles were manufactured. This could potentially cause the barrel to rupture when a cartridge is fired and could result in serious personal injury. The safety of our customers is our primary concern, so Kel-Tec has voluntarily initiated this recall because of the possibility of a barrel rupturing.


This recall only affects a portion of SUB-2000s that were manufactured in 2017.

To check if your firearm would need to be sent in for barrel replacement enter your serial number into the provided field below. Refer to the image at the bottom of this page to help locate your serial number.

All costs associated with the recall of your firearm shall be covered by Kel-Tec.

If you are a dealer and require our FFL, please [Click Here](#) to download a copy.

Submit



**QUICK LINKS**

- SUPPORT
- WARRANTY
- ABOUT
- NEWS
- CONTACT

**STAY CONNECTED**

- FACEBOOK
- TWITTER
- YOUTUBE
- INSTAGRAM

- PRIVACY POLICY
- TERMS OF USE

